

Edge V2

Assembly instructions

WENDELBO

Please note

Please read these instructions carefully and keep them for future reference. Refer to the parts inventory and ensure you have all the parts before starting. During assembly, place all parts on a flat, soft and clean surface, such as a carpet or blanket, to prevent scratches and damage. We recommend that a minimum of two people help each other to assemble.

Parts inventory

A Legs


B Socket head screw

C Allen key



Assembly

Attach the legs (A) by inserting the socket head screws (B) into the predrilled holes, securing them with the Allen key (C). Ensure proper alignment of the connection joints and gently push the modules together. To disassemble, lift the module using the female connection joints and gently pull the modules apart in opposite directions.





WENDELBO

